



DRA ASTRA Construction update photos – May 2025

Over all percentage of Completion

S. No	Project Code	Project Name	Saleable Area in Sqft	Cumulative% Achieved up to May-25	Status
1	DRA-30`	Astra	1,87,894	6%	Foundation Stage



Site top view



Main building – Pour 02 plinth beam reinforcement work in progress



Main building – Pour 03 & 04 pedestal column DPC work completed



Main building – Pour 04 pedestal column concrete work completed.




Main building – Pour 04 soil back filling work completed



Main building – Pour 04 plinth beam pcc work in progress



UG Sump – Cover slab shuttering work in progress



STP – Raft concrete work completed



STP – Column & wall reinforcement work in progress



Setback area soil levelling work in progress

*Thank
you!*