



## BEENA CLOVER

**Monthly Construction Updates – August 2025**

## STAGE COMPLETION STATUS UP TO AUGUST 2025

S. No	Description	Status	Remarks
1	Completion of Foundation	Completed	
2	Completion of Stilt Floor Roof	Progress	
3	Completion of First Floor Roof	Progress	
4	Completion of Second Floor Roof	Progress	
5	Completion of Third Floor Roof	Progress	
6	Completion of Fourth Floor Roof	Progress	
7	Completion of Fifth Floor Roof	Progress	
8	Completion of Masonry Work	Progress	
9	Completion of Internal Plastering	Progress	
10	Completion of Internal Finishes		





**Site Front View**





**Block-1- Elevation View**





**Block-1- Pour 3-Plinth Beam Concrete work in progress**





**Block-1- Pour-1- First Floor Slab Column concrete work & Roof slab shuttering work in progress**





**Block-2- Elevation View**





**Block-2-Pour 2- Plinth beam DPC Work Completed.Soil Filling Work in progress**





**Block-2-Pour 2- Stilt Floor Column Concrete Work in progress**





**Block-2- Pour 1 – Fourth Floor Slab Shuttering Work in Progress**





**Block-2- Pour 1 – Fourth Floor Slab Reinforcement Work in Progress**





**Block-3- Elevation View**





**Block-3 Fifth Floor Block Work in Progress**





**Block-3- Fourth Floor Wall Plastering work in Progress**





**Block-3 Above Terrace Activities in progress**





**Block-4- Elevation View**





**Block-4 First Floor Plastering Work in Progress**





**Block-4- Third Floor Electrical Wall Chasing & Conduit laying work in Progress**





**Block-4 Fourth Floor Above lintel Block work in progress**





**Block-4- Fifth Floor Layout Block Work in progress**





**Block-4- Above Terrace Activities in progress**



*Thank  
you!*