



DRA BEENA CLOVER MONTHLY CONSTRUCTION UPDATES–NOVEMBER 2024

STAGE COMPLETION STATUS UP TO NOVEMBER 2024				
S. No	Description	Status	% of Completion	Remarks
1	Commencement of Foundation	Progress	40 %	
2	Commencement of Stilt Floor Roof			
3	Commencement of First Floor Roof			
4	Commencement of Second Floor Roof			
5	Commencement of Third Floor Roof			
6	Commencement of Fourth Floor Roof			
7	Commencement of Fifth Floor Roof			
8	Commencement of Masonry Work			
9	Commencement of Internal Plastering			
10	Commencement of Internal Finishes			



SITE FRONT VIEW



BLOCK -1- FOOTING & COLUMN CONCRETE WORK IN PROGRESS



BLOCK -1-STP EXCAVATION WORK IN PROGRESS



BLOCK-2-FOOTING & COLUMN CONCRETE WORK IN PROGRESS



BLOCK-2-UG SUMP RAFT CONCRETE WORK IN PROGRESS



BLOCK-3 PLINTH BEAM REINFORCEMENT & CONCRETE WORK IN PROGRESS



BLOCK -4 BACKFILLING WORK IN PROGRESS



RAIN WATER AND SULLAGE TANK COVER SLAB SHUTTERING WORK IN PROGRESS



**EXTERNAL-WEST & NORTH SIDE COMPOUND WALL COLUMN & COPING
BEAM CONCRETE WORK IN PROGRESS**



EXTERNAL-EAST SIDE COMPOUND WALL EXCAVATION COMMENCED

*Thank
you!*