DRA HARMONY CONSTRUCTION UPDATES – JANUARY 2025



CORA HARMONY







Over all percentage of Completion

S. No	Project Code	Project Name	Saleable Area in Sqft	Cumulative% Achieved up to Jan-25	Status
1	DRA-19	Harmony	1,88,014	68 %	Structure & Finishing Ongoing







STAGE COMPLETION STATUS UP TO JANUARY -25

S. No	Description	Status	% of Completion	Remarks
1	Completion of Foundation	Completed	100%	
2	Completion of Stilt Floor Roof	Completed	100%	
3	Completion of Upper Stilt Floor Roof	Completed	100%	
4	Completion of First Floor Roof	Completed	100%	
5	Completion of Third Floor Roof	Completed	100%	
6	Completion of Fifth Floor Roof	Completed	100%	
7	Completion of Seventh Floor Roof	Completed	100%	
8	Completion of Ninth Floor Roof	Completed	100%	
9	Completion of Eleventh Floor Roof	Completed	100%	
10	Completion of Thirteenth Floor Roof			
11	Completion of Masonry Work	Upto 10 th Floor Completed	75%	
12	Completion of Internal Plastering	Upto 7 th Floor Completed	45%	
13	Completion of Internal Finishes	Work In Progress		








West side Elevation





East Side Elevation





South Side Elevation







North Side Elevation





















Tenth Floor Block Work Completed

















Seventh Floor Plastering Work Completed










Eighth Floor Plastering Work On Progress







Plumbing – Second Floor Ledge Wall Work on Progress







Plumbing – Sixth Floor Core Cutting Work on Progress









Waterproofing - First & Second Floor Waterproofing Work Completed









First Floor First Coat Wall Putty Work on Progress








First Floor Wall Tile Work on Progress







External – East Side Trench PCC Work on Progress







