# DRA HARMONY CONSTRUCTION UPDATES - MARCH 2025



**CORA** HARMONY







#### **Over all percentage of Completion**

S. No	Project Code	Project Name	Saleable Area in Sqft	Cumulative% Achieved up to March-25	Status
1	DRA-19	Harmony	1,88,014	72%	Structure & Finishing Ongoing







#### **STAGE COMPLETION STATUS UP TO MARCH -25**

S. No	Description	Status	% of Completion	Remarks
1	Completion of Foundation	Completed	100%	
2	Completion of Stilt Floor Roof	Completed	100%	
3	Completion of Upper Stilt Floor Roof	Completed	100%	
4	Completion of First Floor Roof	Completed	100%	
5	Completion of Third Floor Roof	Completed	100%	
6	Completion of Fifth Floor Roof	Completed	100%	
7	Completion of Seventh Floor Roof	Completed	100%	
8	Completion of Ninth Floor Roof	Completed	100%	
9	Completion of Eleventh Floor Roof	Completed	100%	
10	Completion of Thirteenth Floor Roof	Completed	100%	
11	Completion of Masonry Work	Upto 12 <sup>th</sup> Floor Completed	100%	
12	Completion of Internal Plastering	Upto 10 <sup>th</sup> Floor Completed	55%	
13	Completion of Internal Finishes	Work In Progress	55%	Tiling & Painting Work In progress



DRA

HARMONY

# West side Elevation





#### **East Side Elevation**







# **South Side Elevation**









# **North Side Elevation**











#### **Thirteenth Floor Roof Slab Concrete Work Completed**









# **Terrace Parapet Wall Block Work In Progress**









### **Twelfth Floor Block Work**









## **Tenth Floor Plastering Work Completed**









# **Eleventh Floor Plastering Work In Progress**







#### **Electrical – Eleventh Floor Electrical Wall Chasing Work Progress**







# Waterproofing – Ninth Floor Work In Progress










Ninth Floor – 1<sup>st</sup> Coat Wall Putty Work Completed







# First Floor – 1<sup>st</sup> Coat Ceiling Putty Work In Progress








# **Fifth Floor Wall Tile Laying Work Completed**







#### Wall Tile – Sixth Floor Work In Progress







**Floor Tile - Third Floor Tile Laying Work In Progress** 







# External– Entry Entrance Arch Block Work Completed & Plastering Work In Progress







# **External Plastering Work In Progress**







