



DRA INARA
Monthly Progress Photos –April 2026 – Phase 1



Villa No 3 –Front Elevation View



Villa No 4 –Front Elevation View



Villa No 5 –Front Elevation View



Villa No 6 –Front Elevation View



Villa No 7 –Front Elevation View



Villa No – 8 Front Elevation View



Villa No 9 - Front Elevation View




Villa No 10 – Front Elevation View



Villa No 11- Front Elevation View



Villa No 12 –Front Elevation View



Villa No 13- Front Elevation View



Villa No 14 –Front Elevation View



Villa No 15 –Front Elevation View



Villa No 17 –Front Elevation View



Villa No 18&19 – Club House Front Elevation View

*Thank
you!*



DRA INARA
Monthly Progress Photos –April 2026 – Phase 2



Villa No 47 –Head Room Slab Concrete Pouring Completed



Villa No 48 –Parapet Wall Block Work In Progress



Villa No 49&50- Parapet Wall Column Reinforcement Work In Progress



Villa No -51&52 FF Block Work In Progress



Villa No-53 To 55 Head Room Roof Slab Concrete Pouring Completed



Villa No 56 – FF Block Work In Progress



Villa No 57&58- Head Room Roof Slab Concrete Pouring Completed



Villa No 59 –Head Room Roof Slab Shuttering Work In Progress



Villa No 60 – Head Room Roof Slab Shuttering Work In Progress



Villa No 61 –Head Room Roof Slab Shuttering Work In Progress



Villa No 62–GF Roof Slab Concrete Pouring Work Completed



Villa No –63 GF Block Work Completed



Villa No –64&65 FF Roof Slab Concrete Pouring Completed



Villa No 66–FF Roof Slab Concrete Pouring Completed



Villa No 67 –Head Room Roof Slab Concrete Pouring Completed



Villa No 68&69–FF Block Work In Progress



Villa No 70 – Head Room Slab Concrete Pouring Completed



Villa No 71 –Head Room Roof Slab Concrete Pouring Completed



Villa No 72 –GF Column Concrete Pouring Completed



Villa No 73 –External Plastering Work In Progress



Villa No 74 – External Plastering Work In Progress



Villa No 75 –Parapet Wall Block Work In Progress



Villa No 76 –FF Block Work Completed



Villa No 77 –FF Block Work In Progress



Villa No 78–FF Roof Slab concrete Pouring completed



Villa No 79 –FF Roof Slab Concrete Completed



Villa No 80 –GF Roof Slab Concrete Completed



Villa No 81– GF Roof Slab Concrete Completed

*Thank
you!*



DRA INARA
Monthly Progress Photos –April 2026



Villa No 22 –SF Column Reinforcement work In Progress



Villa No 23 –FF Column Reinforcement work In Progress



Villa No 24- FF Column Reinforcement work In Progress



Villa No 25- FF Roof Slab Shuttering Work In Progress



Villa No 26- SF Column Reinforcement work In Progress



Villa No 27 –Head Room Roof Slab Column Reinforcement Work In Progress



Villa No 28 –Head Room Roof Slab Column Reinforcement Work In Progress



Villa No-29 Head Room Column Concrete work Completed



Villa No 30 – FF Roof Slab Shuttering Work In Progress



Villa No 31- FF Column Reinforcement Work In Progress



Villa No 32 –FF Column Concrete Pouring Completed



Villa No 33- FF Roof Slab Concrete Pouring work Completed



Villa No 34 – Plinth Beam Concrete Pouring work Completed



Villa No 35 –Plinth Beam Concrete Pouring work Completed



Villa No 36–FF Column Reinforcement Work In Progress



Villa No 37 –SF Column Reinforcement Work In Progress



Villa No 38–SF Column Reinforcement Work In Progress



Villa No 39 –Head Room Column Reinforcement Work In Progress



Villa No 40–FF Block Work In Progress



Villa No 41- SF Roof Slab Shuttering work Progress



Villa No 42 –SF Roof Slab Column Concrete Pouring Completed



Villa No 43- FF Roof Slab Concrete Pouring Work Completed



Villa No 44 –FF Block Work Completed



Villa No 45-FF Block Work Completed



Villa No 46–FF Roof Slab Reinforcement Work Progress



Villa No 62-GF Roof Slab Concrete Pouring Completed



Villa No 83 –Basement Back Filling Work In Progress



Villa No 84 –Basement Back Filling Work In Progress



Villa No 85 –Basement Back Filling Work In Progress



Villa No 86–Basement Back Filling Work In Progress



Villa No 87–Basement Backfilling Work In Progress



Villa No 88–Basement Backfilling Work In Progress



Villa No 89–GF Staircase Shuttering Work In Progress



Villa No 90 –GF Staircase Reinforcement Work In Progress



Villa No 91–GF Roof Slab Shuttering Work In Progress



Villa No 92–GF Roof Slab Shuttering Work In Progress



Villa No 93–GF Roof Slab Shuttering Work In Progress



Villa No 94 to 96–GF Roof Slab Concrete Pouring Work Completed



Villa No 97 to 98 –GF Roof Slab Concrete Pouring Work Completed



Villa No 99 to 102–FF Roof Slab Concrete Pouring Work Completed



Villa No 103–GF Column Concrete Pouring Work Completed



Villa No 104–GF Roof Slab Reinforcement Work In Progress



Villa No 106–GF Column Concrete Pouring Work Completed



Villa No 107–Basement Back Filling Work In Progress



Villa No 108–FF Column Concrete Pouring Completed



Villa No 110–Plinth Beam PCC Dressing Work In Progress



Villa No 111–Plinth Beam PCC Dressing Work In Progress



Villa No 112–Plinth Beam PCC Pouring Work In Progress



Villa No 113–Basement Block Work Completed



Villa No 114-FF Column Concrete Pouring Work Completed



Villa No 115–GF Column Concrete Pouring Work Completed



Villa No 116– Basement Block Work Completed



Villa No 117–Plinth Beam PCC Pouring Completed



Villa No 118– GF Column Reinforcement Work Completed



Villa No 119–GF Roof Slab Shuttering Work In Progress



Villa No 120–FF Column Reinforcement Work In Progress



Villa No 121–Plinth Beam Shuttering Work In Progress



Villa No 122–Basement Block Work In Progress



Villa No 123–Basement Block Work Completed

*Thank
you!*



DRA INARA
Monthly Progress Photos –April 2026



Villa No 33 –FF Roof Slab Concrete Pouring work Completed



Villa No 35- Plinth Beam Concrete Pouring work Completed



Villa No 41- SF Roof Slab Shuttering work Progress



**Villa No 43 –FF Roof Slab Concrete work
Completed**



Villa No 82- Plinth Beam PCC Pouring Work In Progress



Villa No 105 – GF Roof Slab Reinforcement Work In Progress

*Thank
you!*