



•DRA INARA

•Monthly Construction Update Progress Photos –November 2025



Karanai Main Road

Villa No -3 Front Elevation View



Villa No 4 - Front Elevation View



Villa No – 5 Front Elevation View



Villa No 4 & 5 Side Elevation view



Villa No-6 Front Elevation View



Villa No-7 Front Elevation View



Villa No-8 Balcony Glass Handrail Fixing Completed



Villa No-9 Balcony Glass Handrail Fixing Completed



Villa No-10 Front Elevation View



Villa No 7 To 11 –Side Elevation Top View



Villa No-11 Balcony Glass Handrail Fixing Completed



Villa No-12 Balcony Glass Handrail Fixing Completed



Villa No-12 Solar Panel Fixing Completed



Villa No 13-South Side Arch Concrete 1st Coat Putty Applying Work In Progress



Villa No 14 – South Side Plastering Work Completed



Villa No 15 – South Side Plastering Work Completed



Karanai Main Road

Villa No 17-East Side Arch Concrete 1st Coat Putty Applying Work In Progress



Villa No 17 – South Side Pebble Texture Applying Work On Progress



Villa No-18&19 Club House GF Roof Slab Shuttering Work In Progress



Phase 2 – villa no 47 GF Roof Slab Reinforcement Work On Progress



Phase 2 – villa no 52 GF Column Concrete Pouring Completed



Phase 2 – villa no 45 Plinth Beam PCC Preparation Work On Progress



Phase 2 – villa no 73&74 GF Roof Slab Reinforcement Work On Progress



Phase 2 – villa no 29 Basement Block Work Completed

PROGRESS PHOTOS

Villa 3 ELEVATION – PREVIOUS WEEK



Villa 3 ELEVATION – THIS WEEK



PROGRESS PHOTOS

Villa 4&5 ELEVATION – PREVIOUS WEEK



Villa 4&5 ELEVATION – THIS WEEK



PROGRESS PHOTOS



Villa 6&11 Top Elevation



Villa 12&13 Top Elevation

PROGRESS PHOTOS



Villa 14&15 Top Elevation



Villa 12&16 Top Elevation

PROGRESS PHOTOS




Villa 17 Front Elevation View



Villa 17 Side Elevation View

PROGRESS PHOTOS

Club House - PREVIOUS WEEK




Club House - THIS WEEK



PROGRESS PHOTOS



**Villa 3 Toilet Tiles Laying
Completed**



**Villa 5 Lift Cabin Fixing
Completed**

PROGRESS PHOTOS



**Villa 9 Toilet Grid False Ceiling
Laying Completed**




**Villa 17 Arch Concrete Base
Applying Work Progress**

PROGRESS PHOTOS



**Villa 4&5 Sliding Window
Fixing Completed**



**Villa 17Plumbing Shaft Cera
Board Fixing Completed**

PROGRESS PHOTOS



Villa 3 Compound Wall Main Gate Fixing Completed



Villa 11 Staircase Granite Laying Progress



Villa 12 2nd Coat Putty Applying Progress



Villa 9 Carparking PCC Completed



**Villa 74 GF Roof Slab
Reinforcement Work Progress**



**Villa 56 GF Roof Slab
Shuttering Work Progress**

PROGRESS PHOTOS



**Villa 52 GF Roof Slab
Reinforcement Work Progress**



**Villa 45 Pedestal Column
Shuttering Work Progress**

PROGRESS PHOTOS



Villa 38 Pile Cab Concrete Completed



Villa 44 Plinth Beam Shuttering Work Progress

PROGRESS PHOTOS



**Villa 29 Basement PCC HDPE
Sheet Laying Work Completed**



**Villa 73 GF Roof Slab
Concrete Completed**

PROGRESS PHOTOS



Villa 52GF Roof Slab Electrical Conduit Laying Work Progress



Villa 59 Back Filling Work Completed

PROGRESS PHOTOS

Villa 3 ELEVATION – PREVIOUS WEEK



Villa 3 ELEVATION – THIS WEEK



PROGRESS PHOTOS

Villa 4&5 ELEVATION – PREVIOUS WEEK



Villa 4&5 ELEVATION – THIS WEEK



PROGRESS PHOTOS



Villa 6&11 Front Elevation



Villa 12&13 Front Elevation

PROGRESS PHOTOS



Villa 14&15 Front Elevation



Villa 6&11 Front Elevation

PROGRESS PHOTOS



Villa 6&11 Front Elevation



Villa 4&17 Front Elevation

PROGRESS PHOTOS



Villa 17 Front Elevation View



Villa 17 Side Elevation View

PROGRESS PHOTOS


Club House- PREVIOUS WEEK




Club House - THIS WEEK



PROGRESS PHOTOS



**Villa 9 Aluminum Window Fixing
Work On Progress**



**Villa 9 Aluminum Window
Fixing Work On Progress**

PROGRESS PHOTOS




**Villa 9 Lift Frame Fixing
Completed**



**Villa 9 Terrace Glass
Handrail Fixing Completed**

PROGRESS PHOTOS



**Villa 9 SF Primer Applying
Work On Progress**



**Villa 6&7 Carparking Soil &
Consolidation Work On Progress**

PROGRESS PHOTOS



**Villa 11 Staircase Granite
Laying On Progress**




**Villa 5&6&7 Carparking PCC
Concrete Work Completed**

PROGRESS PHOTOS



**Villa 17 Flooring Tiles Laying
On Progress**



**Villa 17 Flooring Tiles Laying
On Progress**

PROGRESS PHOTOS



Villa 4&5&6 Rain Water Soak Pit Fixing Completed



Villa 4&5&6 Manhole Chamber Plastering Work On Progress

PROGRESS PHOTOS



**Villa 37 Plinth Beam
Reinforcement Work On
Progress**



**Villa 45 Basement Block
Work Completed**

PROGRESS PHOTOS



**Villa 50 FF Roof Slab
Shuttering Work On Progress**



**Villa 108 Pile Cab Shuttering
Work On Progress**

PROGRESS PHOTOS



**Villa 29 GF Staircase
Shuttering Work On Progress**




**Villa 49 FF Roof Slab
Concrete Completed**

PROGRESS PHOTOS



Villa 57 GF Column Concrete Completed



Villa 56 GF Roof Slab Concrete Work Completed

PROGRESS PHOTOS

Villa 3 ELEVATION – PREVIOUS WEEK



Villa 3 ELEVATION – THIS WEEK



PROGRESS PHOTOS

Villa 4&5 ELEVATION – PREVIOUS WEEK



Villa 4&5 ELEVATION – THIS WEEK



PROGRESS PHOTOS



Villa 6&11 Front Side Elevation



Villa 12&16 Front Elevation

PROGRESS PHOTOS



Villa 4&17 Front Elevation



Villa 11&6 Front Elevation

PROGRESS PHOTOS



Villa 6&16 Front Elevation



Villa 4&6 Front Elevation

PROGRESS PHOTOS



Villa 17 Front Elevation View



Villa 17 Side Elevation View

PROGRESS PHOTOS


Club House - PREVIOUS WEEK



Club House - THIS WEEK



PROGRESS PHOTOS



Villa 4 Door Fixing Work On Progress




Villa 4 to10 Plumbing Shaft Cera Board Fixing Work Completed

PROGRESS PHOTOS




Villa 3 Door Fixing Work On Progress




Villa 9 Door Lock Fixing Work On Progress.

PROGRESS PHOTOS




**Villa 9 SF Primer Applying
Work On Progress**



**Villa 9 Door Fixing Work On
Progress**

PROGRESS PHOTOS



**Villa 17 Staircase Granite
Laying On Progress**




**Villa 15 Plumbing Shaft Cera
Board Fixing Work Completed**

PROGRESS PHOTOS




**Villa 9 Car Parking Flooring
Tiles Laying On Progress.**



**Villa 7 Terrace Balcony Glass
Handrail Fixing Completed**

PROGRESS PHOTOS



Villa 9 Aluminum Sliding Window Fixing Work Progress.



Clubhouse GF Roof Slab Reinforcement Work On Progress

PROGRESS PHOTOS



**Villa 14 Plumbing Shaft Cera
Board Fixing Work Completed**



**Villa 5 Landscape Planter box
Block Work On Progress**

PROGRESS PHOTOS




**Villa 5 Landscape Planter box
Block Work On Progress**




**Villa 9 Landscape Planter
box Block Work On Progress**

PROGRESS PHOTOS



**Villa 14&15 Flooring Tiles
Laying Work On Progress**



**Villa 14&15 Flooring Tiles
Laying Work On Progress**



Club House FF Column Concrete Work Completed



Club House Near North Side Compound Wall Plastering Work Completed

PROGRESS PHOTOS



**Villa 29 GF Roof Slab
Reinforcement Work On
Progress**



**Villa 39 Plinth Beam
Concrete Completed**

PROGRESS PHOTOS



Villa 38 Plinth Beam Concrete Completed




Villa 44 Basement Soil Compacting Work On Progress

PROGRESS PHOTOS



**Villa 45 Basement Back Filling
Work On Progress**



**Villa 40 Plinth Beam
Concrete Completed**

PROGRESS PHOTOS



Villa 46 Pile Cap Concrete Completed



Villa 50 FF Roof Slab Concrete Work Completed

PROGRESS PHOTOS



Villa 49 FF Roof Slab Concrete Completed



Villa 56 GF Roof Slab Concrete Work Completed

PROGRESS PHOTOS



Villa 57 GF Roof Slab Concrete Completed



Villa 50 GF Roof Slab Shuttering Work On Progress

PROGRESS PHOTOS



**Villa 107 Plinth Beam PCC
Completed**



**Villa 108 Plinth Beam
Shuttering Work On Progress**

PROGRESS PHOTOS



**Villa 40 Plinth Beam
Shuttering Work On Progress**



**Villa 103 Plinth Beam
Reinforcement Work On Progress**

PROGRESS PHOTOS



**Villa 45 UG Sump Fixing
Completed**




**Villa 44 Basement Block
Work On Progress**

PROGRESS PHOTOS



**Villa 29 Staircase Shuttering
Work On Progress**



**Villa 57 GF Roof Slab
Reinforcement Work On Progress**



THANKS