



DRA POLARIS Construction update photos – April 2026

MASTER PLAN





North side elevation



South side elevation



East side elevation




West side elevation



Main building – 7th floor Roof Slab concrete completed



Main building – 7th floor roof slab Concrete work completed



Main building – 8th floor column reinforcement work completed



Main building – 8th floor column shuttering work completed



Main building – 8th floor column concrete work completed



Main building – 8th floor slab shuttering work in progress



Main building – 8th floor column reinforcement work in progress



Main building – 8th floor column shuttering work in progress




Main building – 8th floor column concrete work in progress



Main building – 5th floor block work in progress



Main building – 2nd floor DB installation work in progress



Main building – 3rd floor wall chasing & pipe fixing work in progress



Main building – 2nd floor internal plastering completed



*Thank
you!*