



DRA SKYLANTIS
CONSTRUCTION UPDATE PHOTOS – APRIL 2026



VIEW FROM ENTRANCE



ELEVATION NORTH WEST



ELEVATION SOUTH EAST



ELEVATION EAST



BLOCK 1 10TH FLOOR DEEP CLEANING COMPLETED



BLOCK 1 – 13TH FLOOR 2ND COAT PAINTING WORK IN PROGRESS



**BLOCK 1 TERRACE FLOOR LOBBY FALSE CEILING WORK IN
PROGRESS**



BLOCK 1 CORRIDOR LIGHT FIXING WORK IN PROGRESS



BLOCK 2 POUR 1 – UPTO 13TH FLOOR SOAP WASH COMPLETED



BLOCK 2 POUR 1 – UPTO 10TH FLOOR CP & SANITARY FITTINGS WORK IN PROGRESS



BLOCK 2 POUR 1 – UPTO 13TH FLOOR DOOR FIXING COMPLETED



BLOCK 2 POUR 1 – UPTO 3RD FLOOR WASHBASIN WALL TILE LAYING COMPLETED



BLOCK 2 POUR 1 – EXTERNAL LOUVER FIXING COMPLETED



BLOCK 2 POUR 1 – 1ST & 2ND FLOOR 2ND COAT PAINTING WORK IN PROGRESS



BLOCK 2 POUR 1 – EXTERNAL PAINTING 2ND COAT PAINTING COMPLETED



BLOCK 2 POUR 1 – STAIRCASE SS HANDRAIL FINISHING WORK IN PROGRESS



BLOCK 2 POUR 2 – UPTO 11TH TO 13TH FLOOR UPVC WINDOW FIXING WORK IN PROGRESS



BLOCK 2 POUR 2 – 11TH TO 13TH FLOOR DOOR FIXING WORK IN PROGRESS



BLOCK 2 POUR 2 – 11TH FLOOR 1ST COAT EMULSION WORK IN PROGRESS



BLOCK 2 POUR 2 – TERRACE OTS COVERING WORK IN PROGRESS



BLOCK 2 POUR 2 – EXTERNAL 2ND COAT PAINTING WORK IN PROGRESS



BLOCK 2 POUR 2 – EXTERNAL LOUVER FIXING COMPLETED



GYM & MULTIPURPOSE HALL INTERIOR WORK IN PROGRESS



MULTIPURPOSE HALL TILE LAYING WORK IN PROGRESS



NORTH SIDE COMPOUND WALL PLASTERING WORK IN PROGRESS



PODIUM GUTTER PLASTERING COMPLETED



RAMP SCREED CONCRETE COMPLETED



NORTH SIDE GSB COMPACTION WORK IN PROGRESS



WEST SIDE PAVER BLOCK LAYING WORK IN PROGRESS



SCAFFOLDING IN PROGRESS FOR CONNECTING BRIDGE FINISHING WORKS



ENTRANCE ARCH PLASTERING & TEXTURE WORK IN PROGRESS



TRANSFORMER YARD FENCING WORK IN PROGRESS



TRANSFORMER YARD HT CALBE LAYING COMPLETED



STILT FLOOR PODIUM CEILING 2ND COAT PAINTING WORK IN PROGRESS



ENTRANCE AREA FENCING WORK IN PROGRESS

Thank
you!