



DRA SKYLANTIS
CONSTRUCTION UPDATE PHOTOS – AUGUST 2025



EAST SIDE ELEVATION VIEW



NORTH EAST ELEVATION



NORTH WEST ELEVATION



SOUTH EAST ELEVATION



SOUTH SIDE ELEVATION



WEST SIDE ELEVATION



BLOCK 1 - TOP VIEW



BLOCK 2 POUR 1 - TOP VIEW



BLOCK 2 POUR 2 - TOP VIEW



BLOCK 1 – STILT FLOOR PLASTERING PREPARTION WORK IN PROGRESS



BLOCK 1 – EB ROOM CIVIL WORKS COMPLETED



BLOCK 1 – EB SHAFT ELECTRICAL WORKS IN PROGRESS



BLOCK 1 – PLUMBING PIPE ERECTION WORKS IN PROGRESS



BLOCK 1 – STAIRCASE GRANITE WORK IN PROGRESS



BLOCK 1 – UPTO FIFTH FLOOR WASH BASIN GRANITE WORK IN PROGRESS



BLOCK 1 – NINTH FLOOR SECOND COAT PUTTY WORK IN PROGRESS



BLOCK 1 – TENTH FLOOR TILES LAYING WORK IN PROGRESS



BLOCK 1 – ELEVENTH FLOOR TOILET WALL TILES LAYING WORK IN PROGRESS



BLOCK 1 – TERRACE BAY 1 SCREED CONCRETE COMPLETED



BLOCK 1 – TERRACE BAY 2 PU COATING COMPLETED



BLOCK 1 – NORTH SIDE EXTERNAL PLASTERING WORK IN PROGRESS



**BLOCK 2 POUR 1 – UPTO 3RD FLOOR SECOND COAT PUTTY WORK
COMPLETED**



BLOCK 2 POUR 1 – EIGHTH & NINTH FLOOR TILE LAYING WORK IN PROGRESS



**BLOCK 2 POUR 1 – TWELFTH FLOOR SUNKEN FILLING WORK
COMPLETED**



**BLOCK 2 POUR 1 – THIRTEENTH FLOOR SUNKEN WATERPROOFING
WORK IN PROGRESS**



BLOCK 2 POUR 2 – TWELFTH FLOOR ROOF SLAB COMPLETED



BLOCK 2 POUR 2 – THIRTEENTH FLOOR COLUMN CONCRETE WORKS IN PROGRESS



BLOCK 2 POUR 2 – UPTO SIXTH FLOOR BLOCK WORK COMPLETED



**BLOCK 2 POUR 2 – SECOND, THIRD & FOURTH FLOOR INTERNAL
PLASTERING COMPLETED**



BLOCK 2 POUR 2 – SECOND FLOOR WATERPROOFING WORKS IN PROGRESS



WEST SIDE COMPOUND WALL BLOCKWORK COMPLETED



EAST SIDE COMPOUND WALL BLOCKWORK IN PROGRESS



BLOCK 2 POUR 1 EAST SIDE EXTERNAL PLASTERING WORK IN PROGRESS



BLOCK 2 POUR 1 SOUTH SIDE TEXTURE PUTTY WORK IN PROGRESS



BLOCK 2 WEST SIDE TEXTURE PUTTY WORK IN PROGRESS

*Thank
you!*