



DRA TRINITY – CONSTRUCTION UPDATES APRIL 2026

STAGE COMPLETION STATUS UP TO APRIL 2026'

S. No	Description	Status	Remarks
1	Completion of Pile Foundation	Completed	
2	Commencement of Stilt Floor Roof Level	Completed	
3	Commencement of 1st Floor Roof Level	Completed.	
4	Commencement of 2nd Floor Roof Level	Completed.	
5	Commencement of 3rd Floor Roof Level	Completed.	
6	Commencement of 4th Floor Roof Level	Completed.	
7	Commencement of 5th Floor Roof Level	Completed.	



Front View



North Side View.



South Side View.



Main Building Terrace Press Tiles Work In Progress.



Multipurpose Hall Putty Work Completed.



GYM Putty and Grano Flooring Work Completed.



Multipurpose Hall and Gym Room AC Copper Line Work Completed.



Kids Play Area Waterproofing Work Completed.



Main Building Pour-1 1st Floor Flat Door Fixing Work Completed.



Main Building Pour-1 2nd Floor Flat Door Fixing Work Completed.



Main Building Pour-1 3rd Floor Flat Door Fixing Work Completion.



Main Building Pour-1 5th Floor 1st Coat Painting Work Completed.



Main Building Pour-1 4th Floor 1st Coat Painting Work Completed.



Main Building Pour-1 3rd Floor 1st Coat Painting Work Completed.



Main Building Pour-1 2nd Floor 1st Coat Painting Work Completed.



Main Building Pour-1 1st Floor 1st Coat Painting Work Completed.



Main Building Pour-2 1st Floor Putty Work In Progress.



Main Building Pour-2 Stilt Floor Ceiling and Column Primer Work Completed.



**Main Building Pour-1 Electrical 1st Floor Flat Wiring
Work In Progress.**



**Main Building Stilt Floor Electrical Wiring
Work Nearing Completion.**



Main Building Electrical Panel Room Cable Connection Work Completed.



Main Building Pour-1 Stilt Floor Plumbing Work Nearing Completion.



Main Building Pour-2 Stilt Floor Plumbing Work In Progress.



Main Building pour-2 Shaft Pipe Line Work Completed.



Main Building Pour-1 Lift Fixing Work In Progress.



Main Building Pour-2 5th floor Tiles Work In Progress.



Main Building Pour-2 4th floor Tiles Work Completed.



Main Building 1st Floor Corridor Tiles Laying Work Completed.



Main Building 2nd Floor Corridor Tiles Laying Work Completed.



Main Building 3rd Floor Corridor Tiles Laying Work In Progress.



**Main Building Pour-1 Staircase Handrail Fixing
Work Nearing Completed.**



Main Building Pour-2 Staircase Handrail Fixing Work Completed.



**Main Building Plumbing Shaft Shera Plank Covering
Work In Progress.**



Main Building Pour-2 Window Fixing Work In Progress.



Main Building Pour-1 Window Fixing Work In Progress.



**Main Building East Side External Texture Painting
1st Coat Work In Progress.**



**Main Building Pour-2 North Side External Texture Painting
1st Coat Work Completed.**



**Main Building Pour-2 Badminton Court 1st Coat Painting
Work Completed.**



**Main Building Pour-2 South Side External Texture Painting
1st Coat Work In Progress.**



Main Building 9th series External Texture Work Completed.



UG Sump Pump and Pedestal Work Completed.



STP Pump Room Primer Work Completed.



DG Exhaust Pipe Fixing Work In Progress.



Compound Wall Plastering Work Completed.



Storm Water Drain Raft Concrete Work Nearing Completion.

*Thank
you!*